APEX FRIENDSHIP HIGH SCHOOL

WEEK OF 4/07/14 – JOB PROGRESS

SITE:

- 1. Building Access Road Maintenance Ongoing
- 2. Sub-grading of the Football Field Ongoing

SOUTH BUILDING:

- 3. Full Height CMU (South East and South Building) Complete
- 4. Full Height CMU (South West Building)- 95% Complete
- 5. Steel Joist and Decking (South West Building) Ongoing
- 6. MEP in-wall rough-in (South West Building) Complete
- 7. MEP overhead rough-in (South East and South Buildings) Ongoing
- 8. Mechanical Mezzanine AHUs Installed
- 9. Roof Decking (South West Building) Ongoing
- 10. Structural Steel (South Building Column line D) Ongoing
- 11. Wood Blocking and Roof Drains (South East, South Buildings) Ongoing

North Building:

- 12. First, Second, and Third Floor CMU Walls (North East Building 0-5) Ongoing
- 13. First, Second, Third and Fourth Floor MEP Overhead Rough-in (North East Building 0-5) Ongoing
- 14. First, Second, Third and Fourth Floor MEP Overhead Rough-in (North Building 5-13.1) Ongoing
- 15. First and Second Floor In wall Rough-in (North Building 0-5) Ongoing
- 16. First Floor Spray Fireproofing (North West Building 5-13.1) Ongoing
- 17. First, Second and Third Floor Stud Walls (North East Building 0-5) Ongoing
- 18. First Floor Stud Walls (North Building 5-13.1) Ongoing
- 19. First and Second Floor CMU Walls (Stair Tower S1) Complete
- 20. Full Height CMU Walls (Stair Tower S2) Complete
- 21. Full Height CMU Wall and Metal Stair (Stair Tower S3) Complete
- 22. First, Second, and Third CMU (Stair Tower S4) Complete









Installation of Access Roads Ongoing




Full Height CMU Walls throughout the South West Building Are Ongoing



CMU throughout the North Building is Ongoing





NE Building first, Second, Third and Fourth Floor Electrical, Plumbing and Mechanical Rough-in is Ongoing



First, Second, Third Floor (Column Lines 1-5) Metal Stud Walls are Ongoing.



Installation of Structural Steel (South Building Column Line G) is Ongoing



Wood Blocking @ the Roof Parapets are Ongoing
Installation of the Roof Drains are Ongoing